



CLAD REPLACEMENT DOUBLE HUNG

CLAD REPLACEMENT DOUBLE HUNG

Glazing Description		Spacer	U-Value	R-Value	SHGC	VT	N	NC	SC	S
No Grilles, 7/8" and 1 1/4" SDL	Insul LoE 366 W/Argon No Fingerpulls	SS	0.30	3.33	0.18	0.42	Blue	Yellow	Orange	Red
No Grilles, 7/8" and 1 1/4" SDL	Insul LoE 366 W/Argon with Fingerpulls	SS	0.30	3.33	0.18	0.42	Blue	Yellow	Orange	Red
Grilles in Airspace, 7/8" and 1 1/4" SDLB	Insul LoE 366 W/Argon No Fingerpulls	SS	0.30	3.33	0.16	0.37	Blue	Yellow	Orange	Red
Grilles in Airspace, 7/8" and 1 1/4" SDLB	Insul LoE 366 W/Argon with Fingerpulls	SS	0.30	3.33	0.16	0.37	Blue	Yellow	Orange	Red

Values in Green meet the ≤ 0.30 U value and ≤ 0.30 SHGC Tax Incentive Program requirements.

SS = Semco Foam Spacer, XL = Cardinal Stainless Spacer; Units specified with Semco Foam Spacer may at times be converted to Cardinal Stainless Spacer due to unique glass type and/or size constraints. This may or may not affect performance data.