

## CLAD REPLACEMENT DOUBLE HUNG PICTURE

### CLAD REPLACEMENT DOUBLE HUNG PICTURE

Glazing Description			Spacer	U-Value	R-Value	SHGC	VT	N	NC	SC	S
No Grilles, 7/8" and 1 1/4" SDL	3\4mm	Insul LoE 366 W/Argon	SS	0.30	3.33	0.19	0.45	■	■	■	■
No Grilles, 7/8" and 1 1/4" SDL	5mm	Insul LoE 366 W/Argon	SS	0.30	3.33	0.19	0.44	■	■	■	■
No Grilles, 7/8" and 1 1/4" SDL	3\4mm	Insul LoE 240 w/Argon	SS	0.30	3.33	0.18	0.28	■	■	■	■
Grilles in Airspace, 7/8" and 1 1/4" SDLB	3\4mm	Insul LoE 366 W/Argon	SS	0.30	3.33	0.17	0.40	■	■	■	■
Grilles in Airspace, 7/8" and 1 1/4" SDLB	5mm	Insul LoE 366 W/Argon	SS	0.30	3.33	0.17	0.40	■	■	■	■
Grilles in Airspace, 7/8" and 1 1/4" SDLB	3\4mm	Insul LoE 240 w/Argon	SS	0.30	3.33	0.16	0.24	■	■	■	■

Values in Green meet the  $\leq 0.30$  U value and  $\leq 0.30$  SHGC Tax Incentive Program requirements.

SS = Semco Foam Spacer, XL = Cardinal Stainless Spacer; Units specified with Semco Foam Spacer may at times be converted to Cardinal Stainless Spacer due to unique glass type and/or size constraints. This may or may not affect performance data.

Glass Thickness "3/4/5 mm" changes with size of unit. Replacement units are all custom size units. Refer to Clad Double Hung Picture page for comparing unit sizes and glass thicknesses. Call Semco Windows for further information if required.